

## Assembly guide

SNAP female M inset screw  
+ tool 34 & 3

### Logo positioning

Logo marking on tool for  
orientation during screwing

Place and align the fastener  
with logo parallel to an edge.  
Avoid overhead position!

### 1. Prepare hole

### 2. place fastener and fix with tool 34

### 3. Position screw and tighten with tool 3

Section with positioned fastener

recommended cut hole diameter 25 mm  
(recommended - depends on the material in which it is assembled)

ARTICLE NO.	05516-000002 (BLK)
DATE	18.07.2024
AUTHOR	CK

patented technology.